

EXHIBIT D

PHOTOGRAPHS OF EXISTING STRUCTURES



No. 1 - 2508 Thomas

Approx. 1890-95;

Description: Originally Victorian, stripped to frame in 1940's, beige brick, glass block in place of stain glass, 2 story, end chimney, 2nd floor balcony, 12/12, 8/8, 9/9 windows.

Condition: Excellent

Significance: Probably none-altered.



No. 2 - 2512 Thomas

Approx. 1890-95;

Description: Late Victorian, 2 story, main roof-steep hip, intersecting gables, bay pavilions, Ionic porch columns, 2 story Ionic columns at center, fishscale shingles at gable ends, transom side and corner lights, interior chimney, tall 1/1, 2/1 windows, wood porch.

Condition: Excellent.



No. 3 - 2516 Thomas

Approx. 1890-1900;

Description: Late Victorian, main hip roof, gable with bay pavilion, 2 story, wrap porch with hip roof and Doric columns on brick piers, hip dormer, interior chimney, transom, tall 1/1 windows with cornice window heads;

Condition: excellent.



No. 4 - 2600 Thomas

Approx. 1890-1900;

Description: 2 story, tall, narrow 1/1 windows,
Doric style porch columns, covered with siding.

Condition: Good.



No. 5 - 2612 Thomas

Approx. 1890-1900;

Description: 2 story, Craftsman, 1/1, 2/1 windows, 1/1 paired dormer windows, addn. on front, metal awnings added.

Condition: Good.



No. 6 - 2616 Thomas

Approx. 1880-90;

Description: Vernacular Victorian, 1- $\frac{1}{2}$ story, wood frame, steep pitched gable roof, 1/1 windows, 1/1 paired dormer windows; turned porch posts.

Condition: Excellent.



No. 7 - 2613 Thomas

Approx. 1890-1900;

Description: Victorian cottage planbook, steep hip roof with shortridge, intersecting gable, large gable dormer, side chimney, gable end trim, 1/1 windows, wide trim boards.



No. 8 - 2609 Thomas

Approx. 1950-60;

Description: shallow gable roof, smaller front gable projection, boxed extended eaves, beige brick, grillwork porch posts, bowed large 25 pane front windows.

Condition: excellent.

Significance: None - too new.



No. 9 - 2605 Thomas

Approx. 1950-60;

Description: layered hip roof, interior chimney, large picture windows, medium color brick.

Condition: Excellent.

Significance: None - too new.



No. 10 - 2519 Thomas

Approx. 1890-1900;

Description: Victorian cottage planbook, main hip roof with large intersecting gables front and side, shed porch roof with classical columns, turret dormer, angle turned brackets for front window awning, fishscale shingles in gable ends, 1/1 windows, center and side end chimneys.

Condition: Excellent