



No. 11 - 2517 Thomas

Approx. 1900-10;

Description: Craftsman, 2 story, shallow hip roof with extended box eaves, large pediment centered on front, 4 large 2 story square columns, cornice window heads, wide 1/1 windows, transom over double front door, tall side exterior.

Condition: Good.



No. 12 - 2513 Thomas

Approx. 1890-95;

Description: Late Victorian, 2 story, intersecting gables, interior chimney, elaborate gable trim and bargeboard, tall 1/1 windows with elaborate cornice window heads, Doric columns with fluted shafts, center 2 columns are 2 stories tall, fishscale shingle string course, brick porch piers, transom.

Condition: Good.



No. 13 - 2509 Thomas

Approx. 1890-95;

Description: Victorian planbook, steep short-ridge pyramid main roof, front and side gable projections, Doric columns, bay under front gable, front gable end highly decorative with angle trim boards and brackets 6" apart all around, 6" spaced brackets around bay and porch cornice, 1/1 windows with cornice window heads.

Condition: Good - maintained.



No. 14 - 2505 Thomas

Approx. 1895-05;

Description: Planbook, main hip roof with gablet, twin gable projections at sides, center gable pediment, twin side end chimneys, Ionic porch columns, trim scrolls in gable ends new, 1/1 windows.

Condition: Excellent.



No. 15 - 2501-03 Thomas

Approx. 1920-30;

Description: 2 story, beige bricks, quoins, porch and balcony across front, heavy square porch columns, 6/6 windows, intersecting gable roof.

Condition: Good.

Significance: Probably none.



No. 16 - 2311 Routh

Approx. 1905-15;

Description: Planbook, gable roof with exposed rafter hip porch roof, elevated wood front porch, 2 front doors, 1/1 windows, wide trim boards.

Condition: Fair-covered.



No. 17 - 2315 Routh

Approx. 1890-1900;

Description: Craftsman, 2 story, main steep hip roof, side pavilion with hip roof, large central chimney, porches for both stories, 2/2 tall narrow windows, boxed extended eaves, deep trimmed cornice, transom.

Condition: Excellent - restored.



No. 18 - 2317 Routh

Approx. 1910-20;

Description: 2 story, hip roof, 6/6 windows,
15 light front doors, boxed extended eaves,
narrow lap siding, narrow board trim.

Condition: Excellent - restored.



No. 19 - 2321 Routh

Approx. 1915-25;

Description: Shallow pyramid roof, 2 story, 6/6 second floor windows, paired 8 pane windows with 4 pane transom, 2-15 light doors with 3 pane transom, center door with 3 pane transom, medium red brick.

Condition: Excellent - restored.



No. 20 - 2312 Routh

Approx. 1910-20

Description: Planbook, main hip roof with exposed rafters, elevated on piers, wide and narrow lap siding, front porch partially enclosed, turned porch posts.

Condition: Excellent.